Oil Field Environmental Incident Summary

Responsible Party: SAMSON RESOURCES COMPANY **Well Operator:** SAMSON RESOURCES COMPANY

Well Name: LYSTAD 26-163-99H

Field Name: AMBROSE Well File #: 17183

Date Incident:8/12/2014Time Incident:15:21Facility ID Number:County:DIVIDETwp:163Rng:99Sec:26Qtr:

Location Description:

Submitted By: Cooper Hearne Received By:

Contact Person: Brad Rogers

2 W 2ND ST SAMSON PLAZA TULSA, OK 74103-3101

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 73 Barrels 72 Barrels 73 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 9/7/2016 Clean Up Concluded: 8/12/2014

Risk Evaluation:No immediate risk

Areal Extent:

Potential Environmental Impacts:

No sustained environmental impact noted.

Action Taken or Planned:

Standing water was sucked up, and soil was washed with fresh water.

Wastes Disposal Location: Collected produced water will be disposed of at the company SWD. If

soil is to be removed, it with be taken to 13 mile landfill.

Agencies Involved:

Updates

Date: 8/13/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank leak, remained on location within the diking according to the report. NDIC retains oversight.